

## VIVOTEK Product Security Advisory

**Advisory ID:** VVTK-SA-2026-04

**CVE ID:** CVE-2026-22755

**First Published:** September 11, 2026

**Last Update:** October 6, 2026

**Status:** Confirmed

**Revision:** 1.0

## Executive Summary

### Overview:

CVE-2026-22755 affects certain VIVOTEK products that have reached End-of-Life (EOL). These products are no longer under active security support. Based on the current assessment, currently supported VIVOTEK products are not affected by this vulnerability.

### Affected Products:

| Product Models                                                                                                                                                                                                                                                                                                                 | Affected Firmware Versions                                                                                                                                    |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|
| FD8365EHV, FD8365HV, FD9165-HT, FD9171-HT, FD9187-H, FD9187-HT, FD9189-H, FD9189-HM, FD9189-HT, FD9365-EHTV, FD9365-HTV, FD9365-HTVL, FD9371-EHTV, FD9371-HTV, FD9381-EHTV, FD9381-HTV, FD9387-EHTV, FD9387-EHV, FD9387-HTV, FD9387-HV, FD9389-EHMOV, FD9389-EHTV, FD9389-EHV, FD9389-HMOV, FD9389-HTV, FD9389-HV, FD9391-EHTV | 0100a, 0106a, 0106b, 0107a, 0107b_1, 0109a, 0112a, 0113a, 0113d, 0117b, 0119e, 0120b, 0121, 0121d, 0121d_48573_1, 0122e, 0124d_48573_1, 012501, 012502, 0125c |
| FE9180-H, FE9181-H, FE9191, FE9381-EHV, FE9382-EHV, FE9391-EV, FE9582-EHNV                                                                                                                                                                                                                                                     | Same as above                                                                                                                                                 |
| IB9365-EHT, IB9365-HT, IB9365-LPR, IB9371-EHT, IB9371-HT, IB9381-EHT, IB9381-HT, IB9387-EH, IB9387-EHT, IB9387-H, IB9387-HT, IB9387-LPR, IB9389-EH,                                                                                                                                                                            | Same as above                                                                                                                                                 |

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |               |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| IB9389-EHM, IB9389-EHT, IB9389-H, IB9389-HM, IB9389-HT, IB9391-EHT                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |
| IP9165-HP (3.6-17 mm), IP9165-HP (No-Lens), IP9165-HT (3.9-10 mm), IP9165-HT (No-Lens), IP9165-LPC (9-50 mm), IP9165-LPC (12-40 mm), IP9165-LPC (No-Lens), IP9165-LPR, IP9165-LPR (9-50 mm), IP9165-LPR (12-40 mm), IP9171-HP, IP9171-HT, IP9172-LPC (Freeway), IP9181-H (4.1-9 mm), IP9181-H (No-Lens), IP9191-HP (3.9-10 mm), IP9191-HP (No-Lens), IP9191-HT (3.9-10 mm), IP9191-HT (No-Lens), IT9389-H, IT9389-HT, IT9389-H-V2, MA9321-EHTV, MA9322-EHTV, MS9321-EHV, MS9390-HV, TB9330-E (8.8 mm), TB9330-E (19 mm), TB9330-E (35 mm), TB9330-E (50 mm) | Same as above |

**Product Status:** The affected products listed above have reached End-of-Life (EOL), and security support is no longer provided for these models.

**Impact Assessment:** CVE-2026-22755 affects EOL products only. Currently supported products are not affected.

#### **Workaround:**

VIVOTEK recommends that customers follow standard security best practices, including deploying devices in trusted network environments, restricting network exposure, and limiting access to authorized users only.

#### **Solution:**

Replace affected EOL products with currently supported models. Customers should refer to successor products or contact a VIVOTEK sales or support representative for replacement options.

#### **Revision History:**

| Revision | Date               | Description     |
|----------|--------------------|-----------------|
| 0.1      | September 11, 2026 | Initial draft   |
| 1.0      | October , 2026     | First published |