VIVOTEK
A Delta Group Company

Release Note

Product Name:	< FD9369 >
Release Version:	< 1.2201.41.03b >
Date:	< 2026/10/22 >
Product Type	☒ Camera ☐ NVR ☐ Software

New Feature:

- Add memory support

Changed Feature:

- N/A

Bugs Fixed:

- Fixed an issue where motion detection occasionally failed after uploading a backup file.
- Fixed an issue where the camera failed to boot or repeatedly rebooted after a power outage due to a filesystem mount failure.
- Fixed an issue where streaming image abnormal after applying the config file of the camera has different sensors.
- Fixed an issue where frequent recording loss and mount errors across multiple SD card brands.

Relevant module and package information:

- Web API version 0319a
- VADP version 1.5.1.1
- Genetec Protocol version v2.2.1.1
- Onvif version 21.06

Known Issue:

- N/A

Limitation:

- N/A

Important Notice:

- N/A



VIVOTEK
A Delta Group Company

Release Note

Release Version: <1.2201.41.02b>
Date: <2025/08/08>
New Feature:

- Add one-time tracking once to action of camera link
- Support SD card Life Expectancy to Micron400 series.

Changed Feature:

- Enhance SD card write/read architecture to improve the stability of camera operating.

Bugs Fixed:

- Fixed an issue where outdoor cameras would randomly flicker on sunny days.

Relevant module and package information:

- Web API version 0319a
- VADP version 1.5.1.1
- Genetec Protocol version v2.2.1.1
- Onvif version 21.06

Known Issue:

- N/A

Limitation:

- N/A

Important Notice:

- N/A

Release Version: <1.2201.41.01l>
Date: <2024/05/20>
New Feature:

- Support scene search with VIVOTEK NVR and VSS

Changed Feature:

- Update VCA pkg to 7.10.3.7



Bugs Fixed:

- Fixed Security Center authorization fails when the network is unstable.
- Fixed an issue where setting the FPS to 1 on the FD9369/IB9369 prevented the image from being viewed normally.

Relevant module and package information:

- Web API version 0319a
- VADP version 1.5.1.1
- Genetec Protocol version v2.2.1.1
- Onvif version 21.06

Known Issue:

- N/A

Limitation:

- N/A

Important Notice:

- N/A

Release Version: <1.2201.41.01i>
Date: <2023/09/27>
New Feature:

- N/A

Changed Feature:

- N/A

Bugs Fixed:

- Fixed the camera saving IR illuminator configurations despite not clicking the "save" button.
- Fixed an issue that the network QoS settings cannot be saved in the camera web UI.
- Fixed cannot send motion events to Genetec after a period of time.
- Fixed after uploading the configuration, the camera angle will be -999

Relevant module and package information:



- Web API version 0319a
- VADP version 1.5.1.0
- Genetec Protocol version v2.2.1.1
- Onvif version 21.06

Known Issue:
- N/A

Limitation:
- N/A

Important Notice:
- N/A

Release Version: <1.2201.41.01d>
Date: <2022/12/06>
New Feature:
- N/A

Changed Feature:
- N/A

Bugs Fixed:
- Fixed the abnormal audio under certain circumstances

Relevant module and package information:
- Web API version 0319a
- VADP version 1.5.1.0
- Genetec Protocol version v2.2.1.1
- Onvif version 21.06

Release Version: <1.2201.41.01c>
Date: <2022/07/26>
New Feature:



- Added support for SRTP on Genetec Security Center.

Changed Feature:
- Enhanced SD card format mechanism.
- Enhanced the firmware for image sustainability.

Bugs Fixed:
- Fixed the interruption of VADP pkg upgrade via CGI command.
- Fixed the CVE-2022-0778 cyber security issue related to OpenSSL.
- Fixed the snapshot by CGI command is not real time.
- Fixed the VLC stuck or show broken image under certain conditions.

Relevant module and package information:
- Web API version 0319a
- VADP version 1.5.1.0
- Genetec Protocol version v2.2.1.1
- Onvif version 21.06

Release Version: <1.2101.41.01l>
Date: <2021/8/12>
New Feature:
- N/A

Changed Feature:
- N/A

Bugs Fixed:
- Fixed the camera auto reboot after syncing the NTP under certain conditions.

Release Version: <1.2101.41.01k>
Date: <2021/6/15>
New Feature:
- First Release.



Changed Feature:

- N/A

Bugs Fixed:

- N/A

