



VIVOTEK Product Security Advisory

Advisory ID: VVTK-SA-2019-003

CVE ID: CVE-2019-11477, CVE-2019-11478, CVE-2019-11479

First Published: September 6, 2019

Last Update: September 6, 2019

Status: Partial Fixed

Revision: 1

Overview:

CVE-2019-11477, CVE-2019-11478 and CVE-2019-11479 allow remote attackers to conduct denial-of-service attacks. For more information please check following URL.

<https://github.com/Netflix/security-bulletins/blob/master/advisories/third-party/2019-001.md>

Affected Products:

Network Camera:

All Network Camera Series using firmware prior to XXXXXX-VVTK-0X20a.

NVR:

ND Series: ND9541, ND9441, ND9541P, ND9441P, NV9411P, NV9311P, ND8212W, ND8312, ND9312, RX9401, ND9322P, ND9424P.

NR Series: Not affected.

Workarounds:

None.

Solution:

Network Camera:

Please upgrade firmware to XXXXXX-VVTK-0X20a_SA2019002 or above.

NVR:

Still in progress.

Revision History:

Revision 1 / September 6, 2019 / Initial release